

100 mm PVC

100 mm PVC

CONTINUED ON SHEET E6

CONTINUED ON SHEET G6



POSTAL: PO BOX 401 ROMSEY VIC 3434  
EMAIL: JAKE@MRLS.COM.AU  
PHONE: 0403 222 537



WARNING  
ACCURACY OF UNDERGROUND SERVICES INFORMATION  
UNDERGROUND SERVICES SHOWN ON THIS PLAN HAVE BEEN LOCATED TO THE QUALITY LEVEL INDICATED IN THE LINE TYPE DESCRIPTION. THE LOCATION AND DEPTHS STATED SHOULD BE TREATED AS APPROXIMATE AND CAN ONLY BE VERIFIED VIA PROVING METHODS MANUAL EXPOSURE/NON-DESTRUCTIVE DIGGING, Q-LAI OR WHICH UNLESS OTHERWISE AGREED UPON IS THE RESPONSIBILITY OF THE CONTRACTOR.  
THERE IS NO GUARANTEE ALL SERVICES THAT EXIST IN THE AREA COVERED ON THIS PLAN ARE SHOWN.  
THIS PLAN DOES NOT REPLACE BEFORE YOU DIG PLANS

LEGEND

Table with 2 columns: Symbol/Line Type and Description. Includes categories like COMMUNICATIONS, POTABLE WATER, TANK WATER, etc.

Notes

1. TRACEABILITY OF SERVICE MATERIAL TYPES. The ability to locate underground services using electronic /radar detection is heavily dependent on the type of material a given underground service is made from...  
2. INFORMATION REGARDING UNDERGROUND SERVICE DEPTHS. Depths of services provided on this drawing are obtained using electronic detection (L-V) unless otherwise stated. Accuracy of these readings is highly dependent on the environment...  
3. INFORMATION REGARDING UNDERGROUND SERVICE DEPTHS. Depths of storm water and sewer pipes are provided in various manners on this plan. Unless otherwise stated, depths of pipes measured from pit access points/man holes are noted from pit to pipe invert level (I) in mm. In some cases australian height datum (AHD) levels are provided. This can be used to derive the I/AHD of the pipe. In some cases this may already be calculated and noted as AHD (AHD).

WARNING  
ACCURACY OF UNDERGROUND SERVICES INFORMATION  
UNDERGROUND SERVICES SHOWN ON THIS PLAN HAVE BEEN LOCATED TO THE QUALITY LEVEL INDICATED IN THE LINE TYPE DESCRIPTION. THE LOCATION AND DEPTHS STATED SHOULD BE TREATED AS APPROXIMATE AND CAN ONLY BE VERIFIED VIA PROVING METHODS MANUAL EXPOSURE/NON-DESTRUCTIVE DIGGING, Q-LAI OR WHICH UNLESS OTHERWISE AGREED UPON IS THE RESPONSIBILITY OF THE CONTRACTOR.  
THERE IS NO GUARANTEE ALL SERVICES THAT EXIST IN THE AREA COVERED ON THIS PLAN ARE SHOWN.

UNDERGROUND SERVICES (PARTIAL)  
SITE ADDRESS  
SALESIAN COLLEGE SUNBURY  
1 MACEDON ST,  
SUNBURY VIC 3429

PROJECTION: MGA2020 MGA ZONE 55  
HEIGHT DATUM: AHD  
FIELD WORK: JAKE SUTHERLAND  
DRAWN: JAKE SUTHERLAND  
DATE: VARIOUS - SEE COVERSHEET

NOTE  
This master plan is based on data collected from various surveys conducted across the college over an extended period. While an area may indicate the presence of certain services, it may not necessarily reflect all the services present in that area - there may be additional services not shown.  
The focus should be on the idea that "this service has been located and mapped," rather than thinking "this area has been scanned."