

205.53

150 mm VC

100 mm PVC

150 mm VC

CONTINUED ON SHEET E7

CONTINUED ON SHEET C7



POSTAL: PO BOX 401 ROMSEY VIC 3434
EMAIL: JAKE@MRLS.COM.AU
PHONE: 04.03 222 537



ACCURACY OF UNDERGROUND SERVICES INFORMATION
UNDERGROUND SERVICES SHOWN ON THIS PLAN HAVE BEEN LOCATED TO THE QUALITY LEVEL INDICATED IN THE LINE TYPE DESCRIPTION. THE LOCATION AND DEPTHS STATED SHOULD BE TREATED AS APPROXIMATE AND CAN ONLY BE VERIFIED VIA PROVEN METHODS (MANUAL EXPOSURE/NON-DESTRUCTIVE DIGGING, Q.L.A) OF WHICH, UNLESS OTHERWISE AGREED UPON IS THE RESPONSIBILITY OF THE CONTRACTOR.
THIS PLAN DOES NOT REPLACE BEFORE YOU DIG PLANS

LEGEND table with columns for service type and description. Includes entries for POTABLE WATER, TANK WATER, BORE WATER, DAM WATER, etc.

Notes regarding quality levels, service material types, and methods of obtaining depths for storm water & sewer. Includes a detailed explanation of how depth is achieved and how quality levels are defined.

WARNING ACCURACY OF UNDERGROUND SERVICES INFORMATION
UNDERGROUND SERVICES SHOWN ON THIS PLAN HAVE BEEN LOCATED TO THE QUALITY LEVEL INDICATED IN THE LINE TYPE DESCRIPTION. THE LOCATION AND DEPTHS STATED SHOULD BE TREATED AS APPROXIMATE AND CAN ONLY BE VERIFIED VIA PROVEN METHODS (MANUAL EXPOSURE/NON-DESTRUCTIVE DIGGING, Q.L.A) OF WHICH, UNLESS OTHERWISE AGREED UPON IS THE RESPONSIBILITY OF THE CONTRACTOR.
THERE IS NO GUARANTEE ALL SERVICES THAT EXIST IN THE AREA COVERED ON THIS PLAN ARE SHOWN.

UNDERGROUND SERVICES (PARTIAL)
SITE ADDRESS
SALESIAN COLLEGE SUNBURY
1 MACEDON ST,
SUNBURY VIC 3429

PROJECTION: MGA2020 MGA ZONE 55
HEIGHT DATUM: AHD
FIELD WORK: JAKE SUTHERLAND
DRAWN: JAKE SUTHERLAND
DATE: VARIOUS - SEE COVERSHEET

NOTE
This master plan is based on data collected from various surveys conducted across the college over an extended period. While an area may indicate the presence of certain services, it may not necessarily reflect all the services present in that area - there may be additional services not shown.
The focus should be on the idea that "this service has been located and mapped," rather than thinking "this area has been scanned"